

The urine collection tube with the green cap contains boric acid.

Action in the event of accident if contact with boric acid, sodium borate

THE SKIN: Any splash on the skin should be rinsed off with soap and plenty of water. In the event of skin irritation, contact a doctor.

THE EYES: Avoid rubbing the eyes. Rinse immediately with plenty of water or eyewash for at least 10 minutes. Remove contact lenses and keep eyes fully open during rinsing. Seek medical attention if irritation occurs or it continues.

THE MOUTH OR OTHER MUCOUS MEMBRANES: Rinse thoroughly. Seek medical attention if the substance has been swallowed or if you experience uncomfortable sensations.